

Toolkit checklist  
(Not in order of importance)

General work:

1. A CD binder, containing:
    - Windows 98 CD (clean install, not upgrade) and license key
    - Windows 2000 CD (ditto) and license key
    - Windows XP CD (ditto) and license key—this should be a corporate key
    - Other software that you should technically buy, but...
    - Blank CDs
  2. A 5 pack of 3.5" blank floppy disks
    - 2a. A Windows ME boot disk
    - 2b. A Windows ME boot CD-ROM
  3. A small USB memory key
    - 3b. A Windows ME bootable CD key
  4. Mini screwdrivers (rec. German WITA brand)
  5. #2 phillips screwdriver (or screwgun below)
  5. Needle-nose pliers with (anything USA made)
  6. A small cordless drill/screwgun (rec. DeWalt 9.67v)
  7. Ethernet (RJ-45) crimping tool. (rec. any ratcheting style tool)
  8. Spool of Ethernet cable (CAT 5e or higher)
  9. RJ-45 connectors
  10. Electronic labeler with spare tape cartridges
  11. 1 premade 10 ft. Ethernet cable (straight through)
  12. 1 premade 10 ft. Ethernet cable (crossover)
  13. Arrow brand tacking stapler and tacking staples. UL listed.
  14. Spare IDE hard drive
  15. Spare IDE CD ROM
- 
- 
- 
- 
- 
- 
- 
- 

Telco work

1. Punchdown tool
  2. 66-style punchdown blade
  3. 110-style punchdown blade-CUTTING
  4. 110-style punchdown blade-NON-CUTTING
  5. Flathead screwdriver
  6. Line telephone (expensive, but necessary for troubleshooting)
  7. Tone generator and probe (expensive...)
- 
-